### GIS REGISTRY INFORMATION

SITE NAME:	Salvo's Serv	ice S	Station									
BRRTS #:	03-41-00298	10					FID (if a)		priate	e):		
COMMERCE #	53132-9684	-25					(,,	рр. о	pridic	.,.		
(if appropriate):												
CLOSURE DATE:	July 16, 200	4										
STREET ADDRESS:	10125 W Lo	omis	Rd									
CITY:	Franklin											
SOURCE PROPERTY (meters in WTM91 pro		DINA	ATES	X =	67994	3			Y =	2700	46	
CONTAMINATED ME	The state of the s	G	roundwater			Soil			Bot	h	Х	$\neg$
OFF-SOURCE GW C					Yes	_			No		X	
IF YES, STREET A	ADDRESS:										-	
<ul> <li>GPS COORDINAT</li> </ul>		X =					Y =					
(meters in WTM91 pro				1.								
OFF-SOURCE SOIL				Yes	3		No	X				
>Generic or Site-Spe		SHC	L):						-			
<ul> <li>IF YES, STREET A</li> <li>GPS COORDINAT</li> </ul>	A STATE OF THE OWNER, THE PARTY OF THE PARTY	X =					Y =					
(meters in WTM91 pro		^ -					1 -					
CONTAMINATION IN		VAY:	Yes X				No					
OCK I PARTITION IN			DOCUMEN	TS	NEEDE	D	175-25					
Closure Letter, and any con	nditional closure	letter										Х
Copy of most recent deed, i				atad r	roportio			-				X
			1 12	- 0	30							-
Certified survey map or rele	evant portion of t	he rec	corded plat map	(if ret	erenced i	n the legal	descrip	tion) 1	or all a	ffected	properties	Х
County Parcel ID number, I	f used for county	, for a	Il affected prop	erties								X
Location Map which outlines a parcels to be located easily (8.5) potable wells within 1200' of the	x14" if paper copy).	contam If grou	inated site bounda ndwater standards	aries or are e	USGS to ceeded, t	pographic m ne map mus	nap or pl st also in	lat ma nclude	p in suff the loca	icient de ation of a	etail to permit the all municipal and	X
Detailed Site Map(s) for all	affected proper	ties, s	showing buildings,	roads	property	boundaries,	contan	ninant	sources	, utility	lines, monitorin	X
wells and potable wells. (8.5x14 way in relation to the source pro exceeding ch. NR 720 generic or	perty and in relation SSRCLs.	to the	boundaries of gro	undwa	ter contam	ination exce	eeding c	h. NR	140 ES	s and s	oil contamination	Ш
Tables of Latest Groundwa	ter Analytical Re	sults (	no shading or	cross-	hatching	1)						X
Tables of Latest Soil Analyt	tical Results (no	shadii	na or cross-hat	china	)			Ħ				х
Isoconcentration map(s), if	ALL PROPERTY OF THE PARTY OF TH	- Demission	Market Street Street Street Street	Section 1971		pv). The is	oconcer	tration	n map si	hould ha	ave flow direction	- Descriptions
and extent of groundwater contain	mination defined. If	not ava	illable, include th	e lates	t extent of	contamina	ant plun	ne ma	р.			
GW: Table of water level el	levations, with sa	amplin	ng dates, and fro	ee pro	duct not	ed if prese	ent					х
GW: Latest groundwater fl is greater than 20 degrees)		nitorir	ng well location	map	(should l	oe 2 maps	if max	dmun	n varia	tion in	flow direction	X
SOIL: Latest horizontal ext	tent of contamina	ation e	exceeding gene	ric or	SSRCLs	, with one	conto	ar.				X
Geologic cross-sections, it	f required for SI.	(8.5x1	4' if paper copy)									Х
RP certified statement that	legal description	ns are	complete and a	ccura	ite.							Х
Copies of off-source notific	cation letters (if a	pplica	able)			MEE.						
Letter informing ROW own												Х
Copy of (soil or land use) of	deed restriction (	s) or c	leed notice if ar	ıy req	uired as	a conditio	n of cl	osure				X

101 West Pleasant Street, Suite 100A Milwaukee, Wisconsin 53212-3963 TDD #: (608) 264-8777 Fax #: (414) 220-5374 Jim Doyle, Governor Cory L. Nettles, Secretary



July 16, 2004

Mr. Gerald Salvo Salvo's Service Station 10125 West Loomis Road Franklin, WI 53132

RE: Final Closure

Commerce # 53132-9684-25 WDNR BRRTS # 03-41-002980 Salvo's Service Station, 10125 West Loomis Road, Franklin

Dear Mr. Salvo:

The Wisconsin Department of Commerce (Commerce) has received all items required as conditions for closure of the site referenced above. This case is now listed as "closed" on the Commerce database and will be included on the Wisconsin Department of Natural Resources (WDNR) Geographic Information System (GIS) Registry of Closed Remediation Sites to address residual contamination. It is in your best interest to keep all documentation related to the environmental activities that were conducted.

If residual contamination is encountered in the future, it must be managed in accordance with all applicable state and federal regulations. If it is determined that any remaining contamination poses a threat, the case may be reopened and further investigation or remediation may be required.

Thank you for your efforts to bring this case to closure. If you have any questions, please contact me in writing at the letterhead address or by telephone at (414) 220-5376.

Sincerely,

Linda M. Michalets Hydrogeologist

Site Review Section

cc: Mr. Paul Grittner, Dakota Intertek Corp.

Case File

ENVIRONMENTAL & REGULATORY SERVICES DIVISION BUREAU OF PECFA

101 West Pleasant Street, Suite 100A Milwaukee, Wisconsin 53212-3963

TDD #: (608) 264-8777

Fax #: (414) 220-5374 http://www.commerce.state.wi.us http://www.wisconsin.gov Scott McCallum, Governor

Philip Edw. Albert, Secretary



June 26, 2002

Mr. Jerry Salvo Salvo's Service Station 10125 West Loomis Road Franklin, WI 53132

RE:

Conditional Case Closure

Commerce # 53132-9684-25 WDNR BRRTS # 03-41-002980 Jerry Salvo Station, 10125 West Loomis Road, Franklin

Two gasoline underground storage tanks (USTs) removed in 1993; one waste oil and two gasoline USTs removed in 2000

Dear Mr. Salvo:

On May 28, 2002, the Wisconsin Department of Commerce (Commerce) PECFA Site Review Section received a request for case closure from Environmental Innovations, Inc. (EI). It is understood that residual soil and groundwater contamination remains on-site. Using the standards established in the NR 700 series, Wisconsin Administrative Code (Wis. Adm. Code), Commerce has determined that this site does not pose a significant threat to the environment and human health. No further investigation or remedial action is necessary.

### The following conditions must be satisfied to obtain final closure:

- A "Notice of Contamination to Property" that includes a soil deed restriction must be placed on the property deed to address residual petroleum impacts to soil. This deed restriction will require that an institutional control be maintained to prevent the direct contact of petroleum contaminated soil within 4 feet of the ground surface as well as minimize migration of residual petroleum contamination to the groundwater. Commerce requires that you attach Figures 9 and 10 from El's 1999 Remedial Investigation Report to the notification to indicate where the remaining soil contamination exists. Enclosed is an example of a "Notice of Contamination to Property" for your use. Please submit a draft of the "Notice," including the maintenance plan, to this office for approval before recording. If an electronic copy of the "Notice of Contamination to Property" is desired, you may contact Commerce and a copy will be forwarded to you.
- The asphalt cap must be placed on the site in the former UST and dispenser areas where shallow soil contamination remains. Please notify Commerce when the cap has been installed.
- The piezometer and all monitoring wells must be properly abandoned. Please forward the appropriate documentation to the letterhead address.

Mr. Jerry Salvo
Commerce # 53132-9684-25 WDNR BRRTS # 03-41-002980
Jerry Salvo Station, 10125 West Loomis Road, Franklin
June 26, 2002
Page 2

As of August 31, 2001, State Statute 101.143 requires PECFA claimants seeking reimbursement of interest costs to submit a final reimbursement claim within 120 days after they receive written notification that no further action is required with respect to the discharge at their site. This letter serves as your written notice of "no further action". If your claim is not received within 120 days of the date of this letter, interest costs incurred after 60 days of the date of this letter will not be eligible for PECFA reimbursement. Costs associated with recording deed notices or other restrictions are not eligible for PECFA reimbursement, and the recording of these notices should not delay the claim submittal process.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (414) 220-5376.

Sincerely,

Linda M. Michalets Hydrogeologist

1: m. 5

Site Review Section

Enclosure:

"Notice of Contamination to Property"

CC:

Mr. Thomas Pedersen, Environmental Innovations, Inc.

Case File

REEL 4135 TMAR 968 STATE BAR OF WISCONSIN FORM 5 - 1982 DOCUMENT NO. PERSONAL REPRESENTATIVE'S DEED 7418288 REGISTER'S OFFICE } SS -12 30 Pm JACOB J. SALVO and LYXX A. GEIGER, as Co-Personal RECORDED AT\_ Representatives SEP 1 0 1997 APPEN ANKREPTESENIALYS of the estate of REEL 4135 IMAGE 968 969 DOROTHY B. SALVO WASTER BANGE OF DEEDS ..... ("Decedent") common, each holding an undivided 50% interest in Grantee, Milwaukee the following described real estate in .. State of Wisconsin (hereinafter called the "Property): WELLO A-FLAMAGAN mor worth Are milabulery his 58226 Tax Parcel No; A) 864-9984-001 864-9984-002 864-9984-003 SEE ATTACHED EXHIBIT A FOR LEGAL DESCRIPTION B) 841-9999 This conveyance is exempt from the Wisconsin Real Estate Transfer Return filing and fee requirements pursuant to the provisions of Sec. 77.25(11) Wis. Stats. 7418289 # RECORD 12.00 Personal Representative by this deed does convey to Granuee all of the estate and interest in the Property which the Decedent had immediately prior to Decedent's death, and all of the estate and interest in the Property which the Personal Representative has since acquired. August Dated this day of ... (SEAL) Jacob J. Salvo Lynn A. Geiger Personal Zepreseguerre Penogal Representative

AUTHENTICATION	ACKNOWLEDGMENT
Signature(s) Jacob J. Salvo and Lynn A. Geiger, as co-personal representatives	STATE OF WISCONSIN SS.
author cased this 13 day of August 1997	Personally came before me this day of
• Cerald A. Flanagan	
TITLE: MEMBER STATE BAR OF WISCONSIN (If not.	
authorized by § 706.06, Wis. Stats.)	to me known to be the person
THIS INSTRUMENT WAS DRAFTED BY Attorney Gerald A. Flanagan	•
State Bar No. 01006929	Notary Public
(Signatures may be authenticated "sowledged. Both are not necessary.)	My Commission is permanent. (If not, state expiration date:

"Names of persons signing in any capacity should be typed or promot below their signatures.

PERSONAL REPRESENTATIVE'S DEED

#### EXHIBIT A - LEGAL DESCRIPTION

Parcel A:


Parcels One (1), Two (2) and Three (3) of CZRTIFIED SURVEY MAP NO. 2300, of a part of the Northwest-One-quarter (1/4) of Section Twenty (20), in Township Five (5) North, Range Twenty-one (21) East, in the City of Franklin, County of Milwaukee, State of Wisconsin, recorded in the Office of the Register of Deeds for Milwaukee County on April 11, 1974 in Reel 779 at Images 233 to 235 inclusive, as Document No. 4832684.

#### Parcel B

That part of the Southwest One-quarter (1/4) of Section Seventeen (17), in Township Five (5) North, Range Twenty-one (21) East, in the City of Franklin, County of Milwaukee, State of Wisconsin, bounded and described as follows, to-wit: Commencing at the Southeast corner of said 1/4 Section; running thence South 89°55' West on and along the South line of said 1/4 Section, 388.76 feet to a point in the center line of W. Loomis Road; thence North 38°35'45" Zast on and along the said center line, 121.07 feet to a point; thence South 78°27'52" East, 320.39 feet to a point in the East line of said 1/4 Section; thence South 1°18'20" West on and along the said East line, 30.00 feet to the place of beginning, except the Westerly 60 feet thereof (measured at right angles to the center line of W. Loomis Road).

# CERTIFIED SURVEY MAP NO. 6483

A REDIVISION OF LOT 1, 2 AND 3 OF CERTIFIED SURVEY MAP 2300, BEING PART OF THE NE 1/4 OF THE NW 1/4 OF SECTION 20, TOWNSHIP 5 NORTH, RANGE 21 EAST, IN THE CITY OF FRANKLIN, MILWAUKEE COUNTY, WISCONSIN.




A ST


Rust Environment & Intrastructure Inc.

THIS INSTRUMENT WAS DRAFTED BY ROBERT F. SCHMALZER, S-1760, PROJECT NUMBER 102383

SUPPLETOR: 1026 N. BROADWAY SUITE 6"3 MILWAUKEE W 13202

Sheet 1 of 3





TER 6/00

# TABLE 1 (1 of 4) Monitoring Well Groundwater Results

Salvo's 10125 W. Loomis Rd. Franklin, WI.

	ES	PAL			M	W-1					M	W-2		
Compound			8/23/98	1/27/99	3/8/00	2/21/01	5/9/01	11/7/01	8/23/98	1/26/99	3/8/00	2/21/01	5/9/01	11/7/01
GRO (mg/kg)	NS	NS	20,000	16000	16300	NT	NT	NT	1,500	23,000	24,800	NT	NT	NT
DRO (mg/kg)	NS	NS	NT	NT	1010	NT	NT	NT	NT	NT	270	NT	NT	NT
Benzene	5	0.5	5,600	320	5350	2780	3440	1860	<31	0.41	<210	<.44	<.50	1.14
1,2-Dichloroethane	5	0.5	<290	<4.4	166	NT	NT	NT	<58	< 0.44	<120	NT	NT	NT
Ethylbenzene	700	140	600	23	493	227	239	154	<35	< 0.35	<330	<.57	<.50	0.77
Methyl Tertiary Butyl Ether	60	12	14,000	920	14900	14500	16800	12900	4,000	62,000	52,800	24	55,000	44,300
Toluene	1000	200	1,400	16	158	<88	97	31.5	<32	< 0.32	<340	<44	<.50	<.5
Trimethyl Benzene (1,2,4 & 1,3,5)	480	96	<190	6.9	129	<126	175.3	49.52	<38	<.38	<340	<.63	<1.0	<1
Total Xylenes	10000	1000	1,660	46	948	140	359	142	<73	< 0.73	<700	<1.0	<.50	
p-Isopropyltoluene	NS	NS	<180	NT	NT	NT	NT	NT	<37	NT	NT	NT NT	NT	<.5 NT

### NOTES:

NT - Not Tested

NS - No Standard

ES - WDNR NR 140 Enforcement Standards

PAL - Preventive Action Limit

Bolded and boxed values exceed ES

Bolded values exceed PAL

Results reported in micrograms per liter (ug/l) except where otherwise noted.

All other VOC compounds analyzed were below the laboratory minimum detection limits

# TABLE 1 (2 of 4) Monitoring Well Groundwater Results

Salvo's 10125 W. Loomis Rd. Franklin, WI.

	ES	PAL			M	W-3					PZ-3					MW-4		_
Compound			8/23/98	1/26/99	3/8/00	2/21/01	5/9/01	11/6/01	8/23/98	1/26/99	3/8/00	5/9/01	11/6/01	8/29/98	1/26/99	3/8/00	5/9/01	11/8/01
GRO (mg/kg)	NS	NS	540	130	762	NT	NT	NT	27	<20	<14	NT	NT	<20	<20	<14	NT	NT
DRO (mg/kg)	NS	NS	NT	NT	282	NT	NT	NT	NT	NT	177	NT	NT	NT	NT	210	NT	NT
Benzene	5	0.5	84	270	20	69	25.9	23.8	0.81	0.57	< 0.42	3.94	<.5	<0.31	<0.31	< 0.42	< 50	111111111111111111111111111111111111111
1,2-Dichloroethane	5	0.5	<12	<0.44	<2.4	NT	NT	NT	< 0.58	< 0.44	< 0.24	NT	NT	1.4	<0.44	< 0.24	NT	<.5 NT
Ethylbenzene	700	140	15	23	<6.6	<11	3.65	3.68	< 0.35	< 0.35	< 0.66	<.50	<.5	0.45	<0.35	< 0.66	<.50	10000
Methyl Tertiary Butyl Ether	60	12	520	1,400	1,180	2,420	2,870	2,750	0.9	0.72	< 0.35	5	<.5	1.1	0.85	0.48		<.5
Toluene	1000	200	20	6.1	<6.8	<.44	0.574	0.613	<0.32	< 0.32	< 0.68	1.69	<.5	0.36	<0.32	<0.68	14.6	0.781
Trimethyl Benzene (1,2,4 & 1,3,5)	480	96	<7.6	9.4	<6.8	<.63	<1.0	1.76	0.92	<.38	<.68	<1.0	<1	<0.52	<.38	<.68	<.5	<.5
Total Xylenes	10000	1000	60	11.1	<14	< 9.5	2.16	2.25	<0.73	< 0.73	<1.4	1.4	<.5	1.93		100000	<1.0	<1
p-Isopropyltoluene	NS	NS	<7.4	NT	NT	NT	NT	NT	<.37	NT	NT	NT	NT	<.37	<0.73 NT	<0.61 NT	<.5 NT	<.5 NT

#### NOTES:

NT - Not Tested

NS - No Standard

ES - WDNR NR 140 Enforcement Standards

PAL - Preventive Action Limit

Bolded and boxed values exceed ES

Bolded values exceed PAL

Results reported in micrograms per liter (ug/l) except 1

All other VOC compounds analyzed were below the la

# TABLE 1 (3 of 4) Monitoring Well Groundwater Results

Salvo's 10125 W. Loomis Rd. Franklin, WI.

	ES	PAL			MW-5					MW-6				M	N-7			M	W-8	-
Compound			1/27/99	3/8/00	2/21/01	5/9/01	11/7/01	1/27/99	3/8/00	2/21/01	5/9/01	11/7/01	1/27/99	3/8/00	5/9/01	11/6/01	1/27/99	3/8/00	5/9/01	11/6/01
GRO (mg/kg)	NS	NS	26000	36300	NT	NT	NT	33000	30500	NT	NT	NT	<20	<14	NT	NT	<20	<14	NT	1700000
DRO (mg/kg)	NS	NS	NT	169	NT	NT	NT	NT	2660	NT	NT	NT	NT	109	NT	NT	260	443	NT	NT NT
Benzene	5	0.5	<160	<420	<.44	<.50	<.5	5300	5460	7720	8210	4220	< 0.31	< 0.42	<.50	<.5	< 0.31	< 0.42	<.50	N1   <5
1,2-Dichloroethane	5	0.5	<290	<240	NT	NT	NT	<290	180	NT	NT	NT	< 0.58	< 0.24	NT	NT	< 0.58	< 0.24	NT	NT
Ethylbenzene	700	140	<180	<660	<.57	<.50	<.5	<180	220	418	355	205	< 0.35	< 0.66	<.50	<.5	<0.35	< 0.66	<.50	<.5
Methyl Tertiary Butyl Ether	60	12	44000	75500	78700	69800	61000	23000	35600	25700	23800	24500	< 0.29	0.57	<.20	<5	0.98	1.4	2.59	2.46
Toluene	1000	200	<160	<680	<.44	<.50	<.5	4100	1240	4640	3380	432	< 0.32	< 0.68	<.50	<.5	< 0.32	< 0.68	<.50	200000
Trimethyl Benzene (1,2,4 & 1,3,5)	480	96	<350	<680	<.63	<1.0	<1	<260	<227	<316	516	179.6	<.38	<.68	<1.0	<1	<.38	<.68	<1.0	<.5 <1
Total Xylenes	10000	1000	<360	<1400	910	<.50	<.5	1400	657	2440	2110	1070	< 0.73	< 0.61	<.50	<.5	< 0.73	<0.61	7300	
p-Isopropyltoluene	NS	NS	<180	NT	NT	NT	NT	<180	NT	NT	NT	NT	<.37	NT	NT	NT	<.37	NT	<.50 NT	<.5 NT

#### NOTES:

NT - Not Tested

NS - No Standard

ES - WDNR NR 140 Enforcement Standards

PAL - Preventive Action Limit

Bolded and boxed values exceed ES

Bolded values exceed PAL

Results reported in micrograms per liter (ug/l) except v

All other VOC compounds analyzed were below the la

# TABLE 1 (4 of 4) Monitoring Well Groundwater Results

Salvo's 10125 W. Loomis Rd. Franklin, WI.

	ES	PAL		MW-9		MV	V-10		TW-1			TW-2		TW-3	Sump	Sump 2	Pump	Trip Blank
Compound			3/8/00	5/4/00	11/6/01	3/8/00	5/4/00	5/24/00	5/9/01	11/7/01	5/24/00	5/9/01	11/7/01	5/4/00	11/8/01	11/8/01	11/8/01	2/21/01
GRO (mg/kg)	NS	NS	<14	<14	NT	<14	<14	<14	NT	NT	<14	NT	NT	<14	NT	NT	NT	
DRO (mg/kg)	NS	NS	187	82	NT	730	1,160	138	NT	NT	158	NT	NT	NT	NT	NT	NT	NT NT
Benzene	5	0.5	< 0.42	< 0.42	<.5	< 0.42	< 0.42	< 0.42	<.50	<.5	< 0.42	<.50	<.5	< 0.42	<5	<.5	<.5	1.7
1,2-Dichloroethane	5	0.5	< 0.24	NT	NT	< 0.24	NT	< 0.24	NT	NT	< 0.24	NT	NT	NT	<5	<5	<.5	NT
Ethylbenzene	700	140	< 0.66	< 0.66	<.5	< 0.66	< 0.66	< 0.66	<.50	<.5	< 0.66	<.50	<.5	< 0.66	<5	<.5	<.5	1.7
Methyl Tertiary Butyl Ether	60	12	< 0.35	0.83	<.5	< 0.35	< 0.35	< 0.35	<.20	<.5	< 0.35	< 20	<.5	< 0.35	<5	<.5	<.5	2.3
Toluene	1000	200	< 0.68	< 0.68	<.5	< 0.68	< 0.68	< 0.68	<.50	<.5	< 0.68	<.50	<.5	< 0.68	<.5	<.5	<.5	2.0
Trimethyl Benzene (1,2,4 & 1,3,5)	480	96	<.68	<.68	<1	<.68	<.68	< 0.68	<1.0	<1	< 0.68	<1.0	<1	< 0.68	<1.0	<1.0	<1.0	3.8
Total Xylenes	10000	1000	< 0.61	<1.4	<.5	< 0.61	<1.4	<1.4	<.50	<.5	<1.4	<.50	<5	<1.4	<.5	<5	<.5	6.3
p-Isopropyltoluene	NS	NS	NT	NT	NT	NT	NT	NT	NT	NT	NT	NT	NT	NT	1.52	<5	<.5	NT

#### NOTES:

NT - Not Tested

NS - No Standard

ES - WDNR NR 140 Enforcement Standards

PAL - Preventive Action Limit

Bolded and boxed values exceed ES

Bolded values exceed PAL

Results reported in micrograms per liter (ug/l) except v

All other VOC compounds analyzed were below the la

## TABLE 1 (1 of 2) Soil Analytical Results

Salvo's 10125 W. Loomis Rd. Franklin, WI

restriction to any agency	WDNR	G)	P-1	G	P-2	GP-3	G	P-4 maintain	I G	P.Sanitali
	Clean-up	3-5'	5-7'	3-5'	5-7'	5-7	-	5 7		CONTRACTOR SOLUTION
Compound	Standard	7/8/98	7/8/98	7/8/98	7/8/98	7/8/98	7/8/98	7/8/98	7/8/98	7/8/09
GRO (mg/kg)	100	1,300	29	1,800	210	ND	57	120	35	80
DRO (mg/kg)	100	NT	NT	NT ,	NT	NT	NT	NT	NT	NT
Lead (mg/kg)	50	14	5.2	8.3	9.4	5.2	5	8	5.1	6.5
Methyl Tertiary Butyl Ether (MTBE)	NS	2800	6,900	1,900	2,100	ND	7,100	39,000	380	220
Benzene	5.5	24,000	2,000	8,900	4,400	ND	4,600	5,600	500	2,200
Toluene	1,500	92,000	570	19,000	840	ND	6,100	220	410	780
Ethylbenzene	2,900	64,000	430	31,000	3,200	ND	2,300	3,400	1,800	3,700
Total Xylenes	4,100	288,000	1,690	139,000	11,700	ND	12,200	1,700	2,850	11,400
1,3,5 Trimethyl Benzene	NS	49,000	280	31,000	2,100	ND	160	1,200	740	2,000
1,2,4 Trimethyl Benzene	NS	97,000	870	97,000	11,000	ND	450	1,800	3,000	
n-Butylbenzene	NS	NT	NT	NT	NT	NT	NT	NT NT	NT	7,200 NT
Notes		\$#	#	\$#	\$#	0.000	#	111	\$#	#

#### NOTES:

ND - Not Detected

NT - Not Tested

NS - No Standard

- \$ Other heavier hydrocarbons present after the GRO window.
- # Other lighter hydrocarbons present before the GRO window.
- \* The DRO GC chromatogram does not match the diesel standard pattern.

All results reported in micrograms per kilogram (ug/kg) except where otherwise noted.

Bolded values exceed WDNR NR 720 Soil Standards.

**Environmental Innovations** 

By: CKP

Checked By: LD

## TABLE 1 (2 of 2) Soil Analytical Results

Salvo's 10125 W. Loomis Rd. Franklin, WI

	WDNR	GP-6	GP-7	GP-8	GP-9	GP-10	GP-11	GP-12	MW-5	MW-6	MW-7	MW-8
	Clean-up	5-7'	5-7'	3-51	3-5'	3-5'	3-5'	3-5'	5-71	8:10	2270	10.750!
Compound	Standard	7/8/98	7/8/98	7/8/98	7/9/98	7/9/98	THE RESERVE OF THE PARTY OF THE	THE RESIDENCE OF THE PARTY OF T	12/10/98		12/10/98	12/10/98
GRO (mg/kg)	100	1.5	2	ND	69	ND	ND	NT	ND	1.7	ND	ND
DRO (mg/kg)	100	NT	NT	NT	NT	, NT	NT	13	NT	NT	NT	NT
Lead (mg/kg)	50	5.1	5.2	9.2	13	4.4	7.8	11	NT	NT	NT	NT
Methyl Tertiary Butyl Ether (MTBE)	NS	80	2,100	26	ND	ND	ND	ND	5,300	5,500	45	ND
Benzene	5.5	59	19	24	470	ND	20	ND	ND	ND	ND	ND
Toluene	1,500	120	ND	ND	42	ND	ND	ND	ND	ND	ND	ND
Ethylbenzene	2,900	40	ND	ND	120	ND	17	ND	ND	ND	ND	ND
Total Xylenes	4,100	138	ND	ND	140	ND	ND	ND	ND	ND	ND	ND
1,3,5 Trimethyl Benzene	NS	ND	ND	ND	63	ND	17	ND	ND	ND	ND	ND
1,2,4 Trimethyl Benzene	NS	30	ND	ND	31	ND	26	ND	ND	ND	ND	ND
n-Butylbenzene	NS	NT	NT	NT	NT	NT	NT	27	NT	NT	NT	NT
Notes					\$#			*				8/8

### NOTES:

ND - Not Detected

NT - Not Tested


NS - No Standard

- \$ Other heavier hydrocarbons present after the GRO window.
- # Other lighter hydrocarbons present before the GRO window.
- \* The DRO GC chromatogram does not match the diesel standard pattern.

All results reported in micrograms per kilogram (ug/kg) except where otherwise noted. Bolded values exceed WDNR NR 720 Soil Standards.


Environmental Innovations

By: CKP Checked By: LD 5/6/99 1998GEOP.XLS Sheet1



### Legend

##W-3 Monitoring Well 2870 MBTE Concentration (ug/l)



Environmental Innovations, Inc.

### Groundwater MBTE Concentration May 9, 2001

Salvo's 10125 W. Loomis Road Franklin, WI

Figure 3

G:\Phasell\Salvos\Drawings\Groundwater MBTE concentration.dwg

### TABLE 1 Groundwater Elevation Data

Salvo's 10125 W. Loomis Road Franklin, WI


Welf	Top of	密鳞绵	100	C March		Depth (	o Water	visita C	量が出	ADDRESS OF	(f,y)(h)	DE SON	en en la	(1 destable)	STEEL STREET	Water Tab	le Elevation	Maria .	Main with	milita (da)	<b>化发</b> 点:
Vurnber	n) gales:	8/23/1998	8/29/1996	1/26/1999	4/14/1999	3/8/2000	4/25/2000	5/4/2000	5/24/2000	2/20/2001	5/9/2001	8/23/1998	8/29/1998	1/26/1999	4/14/1999	3/8/2000	4/25/2000	5/4/2000	5/24/2000	2/20/2001	5/9/200
MW-1	101.01	6.42	5.99	5.89	4.65	5.27	3.80	4.37	3.68	5.18	4.38	94 59	95 02	95.12	96 36	95.74	97.21	96.64	97.33	95.83	96.63
MW-2	101.00	12.25	14.99	7.10	6.25	8.25	6.61	6.10	5,30	6.04	5.39	88.75	86 01	93.90	94.75	92.75	94.39	94.90	95.70	94.96	95.61
MW-3	101.03	4.25	5.26	5.32	3.71	4.35	3.00	3.45	2.92	5.85	4.44	96.78	95,77	95.71	97.32	96.68	98.03	97.58	98.11	95.18	96.59
MW-4	100.21	NI	4.92	2,15	2.78	3.76	2.25	2.91	2.98	3.57	3.84	NI	95.29	98.06	97.43	96.45	97.96	97.30	97.23	96.64	96.37
MW-5	100.69	NI	NI	6.60	5.97	3.81	5.27	5.67	5.31	5,12	6.48	NI	NI	94.09	94.72	96.88	95.42	95.02	95.38	95.57	94.21
MW-6	100.64	NI	NI	3.58	1.75	2.55	0.52	0.84	0.81	2.40	2.64	NI	NI	97.06	98.89	98 09	100.12	99 80	99.83	98.24	98.00
MW-7	100.57	NI	NI	6.19	5.52	5.71	4.84	5.18	5.00	4.90	4.82	NI	NI	94 38	95.05	94.86	95.73	95.39	95.57	95.67	95.75
MW-8	100.58	NI	NI	4.70	3.58	5.02	2.85	3.11	3.20	3,84	3.87	NI	NI	95.88	97.00	95.56	97.73	97.47	97.38	96,74	96,71
MW-9	101.07	NI	NI	NI	NI	7.20	5.79	6.14	5.05	5.36	5.44	NI	NI	NI	NI	93.87	95.28	94.93	96.02	95.71	95.63
MW-10	102.01	NI	NI	NI	NI	2.26	2,15	2.89	2.85	3,10	2.87	NI	NI	NI	NI	99.75	99.86	99.12	99.16	98.91	99.14
TW-1	101.90	NI	NI	NI	NI	NI	NI	Dry	6.10	NR	5.67	NI	NI	NI	NI	NI	NI	Dry	95.80	NR	96.23
TW-2	100.56	NI	NI	NI	NI	NI	NI	9.45	3.67	NR	4.06	NI	NI	NI	NI	NI	NI	91.11	96.89	NR	96.50
TW-3	101.00	NI	NI	NI	NI	NI	NI	5.91	5.30	NR	NR	NI	NI	NI	NI	NI	NI	95.09	95,70	NR	NR
PZ-3	101.11	27,10	24.86	9.60	10.30	11.17	11.23	10.18	8.82	7.64	7.97	74 01	76 25	91 51	90 81	89.94	89.88	90.93	92.29	93.47	93.14


#### Notes:

Elevations are based on local site datum arbitrarily set to 100 feet

NI = Well not installed

Environmental Innovationa Inc By: TWP Checked By: PVG





### Legend

⊕ MW-3 Monitoring Well 96.59 Groundwater Table Elevation





Environmental Innovations, Inc.

Groundwater Flow Map May 9, 2001

> Salvo's 10125 W. Loomis Road Franklin, WI


G:\PhaseH\Salvos\Drawings\sits\_ust.dwg






Environmental Innovations, Inc.

u:shared\projects\active\Salvo's\USTpull\xsecloc.dwg



Drawn by BPK

Franklin, WI



file: U:\shared\projects\sctive\Selvos\drawings\zeecb.dwg

Drawn by BPK



## ENVIRONMENTAL INNOVATIONS, INC. (EI)

Consulting, Remediation and Industrial Services
14000 Leetsbir Road Sturtevant, WI 53177 262-886-4800, FAX 262-886-4442

May 23, 2002

Ms. Vicky Stovall Remediation & Redevelopment Program Wisconsin Dept. of Natural Resources 2300 N. Dr. Martin Luther King Jr., Dr. Milwaukee, WI 53212

RE: Site: Salvo's Service Station, 10125 W. Loomis Road, Franklin, WI PECFA Claim # 53132-9684-25, BRRTS # 03-41-002980

Closure Documentation

Dear Ms. Stovall:

Enclosed, please find GIS documentation for the above referenced property. Contamination originating at this property appears to be contained within its boundaries. The legal description for this property is attached as certified by the responsible party below.

Note that the parcel identification number for the property is: 8 and the geographic position coordinates (in WTM91 projection) are: 6

846-9984-005 679943, 270046

Sincerely,

Environmental Innovations, Inc.

Thous Wolled

Thomas Pedersen, P.G., P.H.

Technical Manager

I certify that the legal descriptions that are attached to the statement are complete and accurate.

Jerry Salvo Owner Salvo's Service Station



## ENVIRONMENTAL INNOVATIONS, INC. (EI)

Consulting, Remediation and Industrial Services 14000 Leetsbir Road Sturtevant, WI 53177 262-886-4800, FAX 262-886-4442

June 24, 2002

Mr. Ken Wade Wisconsin Dept. of Transportation Trans. District Two 2000 Pewaukee Road P.O. Box 798 Waukesha, WI 53187-0798

RE: <u>Notification of Groundwater Contamination</u>, State Highway 36 (Loomis Road) Right-of-Way, Salvo's Service Station, 10125 W. Loomis Road, Franklin, WI

Dear Mr. Wade:

Environmental Innovations, Inc. was retained by Mr. Gerry Salvo, owner of the above referenced site, to complete an environmental investigation due to a petroleum release from a gasoline/waste oil Underground Storage Tank (UST). The purpose of this letter is to notify you that residual groundwater contamination remains along the Loomis Road right-of-way, as depicted on the attached map. Benzene concentration in the water collected and analyzed from monitoring well MW-6 was detected at 4,220 ug/l on 11/7/01. Due to the high benzene concentration in the groundwater at MW-6 any dewatering activities conducted in the vicinity of this well may require that the water be collected for subsequent treatment or disposal.

Furthermore, Methyl tert-butyl ether (MTBE) contamination may be present within the right-of-way boundary near MW-6 at elevations beneath the watertable. Specifically, MTBE was detected at 5,500 ug/kg within the soil at a depth of 8-10 ft below ground surface (BGS) at MW-6. The groundwater table is only 1.5 ft BGS at that location.

If you have any questions or concerns regarding this matter, please contact this office at (262) 886-4800. Thank you for your time.

Sincerely,

Environmental Innovations, Inc.

Thom W. Dula

Thomas Pedersen, P.G. Technical Manager

attachment - Figure 1

### NOTICE OF CONTAMINATION TO PROPERTY

Legal Description of the Property: In re:

#### Parcel A:

Parcels One (1), Two (2) and Three (3) of CERTIFIED SURVEY MAP No. 2300, of a part of the Northwest One-quarter (1/4) of Section Twenty (20), in Township Five (5) North, Range Twenty-one (21) East, in the City of Franklin, County of Milwaukee, State of Wisconsin, Recorded in the office of the Register of Deeds for Milwaukee County on April 11, 1974 in Reel 779 at Images 283 to 285 inclusive, as Document No. 4832684.

### Parcel B:

That part of the Southwest One-quarter (1/4) of Section Seventeen (17), in Township Five (5) North, Range Twenty-one (21) East, in the City of Franklin, County of Milwaukee, State of Wisconsin, bounded and described as follows, to-wit: Commencing at the Southeast corner of said 1/4 Section; running thence South 89°55' West on and along the South line of said 1/4 Section, 388.76 feet to a point in the center line of W. Loomis Road; thence North 38°35'45" East on and along the said center line, 121.07 feet to a point; B) 841-9999 thence South 78"27'52" East, 320.39 feet to a point in the East line of said 14 Section; thence South 1°18'20" West on and along the said East line, 30.00 feet Parcel Identification Number (PIN) to the place of beginning, except the Westerly 60 feet thereof (measured at right angles to the center line of W. Loomis Road).

8345418

REGISTER'S OFFICE. 1 SS Milwaukee County, WII RECORDED AT 1:10 PM 09-13-2002

IGNATIAS J. NIENCZYK REGISTER OF DEEDS

AMOUNT 19.00

### Recording Area

Name and Return Address Gerald Salvo 10125 West Loomis Road

Franklin, WI 53132

A) 864-9984-001, 864-9984-002, 864-9984-003

STATE OF WISCONSIN

COUNTY OF MILWAUKEE

Section 1. Lynn A. Geiger and Gerald J. Salvo are the owners of the above-described property.

SS

Section 2. One or more petroleum discharges have occurred at this property. Petroleum contaminated soils with concentrations that exceed NR 720 residual conceminant levels and Comm 46 direct contact levels of the Wisconsin Administrative Code exist on this property. The data for this site (Commerce # 53132-9684-25, WDNR BRRTS # 03-41-002980) were presented in reports prepared by Environmental Innovations, Inc.

The owners hereby declare that all of the property described above is held and shall be held, conveyed or Section 3. encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Petroleum contaminated soil remains on this property in the vicinity of the former gasoline underground storage tanks (USTs) and dispensers (see the attached figures). An impermeable cap or cover is the selected remedial action to address residual soil contamination that poses a direct contact threat at the property. Therefore, an impermeable cap or cover (i.e. conc. etc. asphalt) shall be maintained across this property until: 1) the soil is actively remediated or removed or; 2) it can be shown that the soil has naturally degraded to levels shown to be protective of the environment and human health. If subsurface work is done in the contaminated areas, the contamination shall be managed in accordance with applicable laws.

The property owner shall maintain the integrity of the [construction type] cap in the following manner: [Description of the maintenance plan.]

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 22 day of August 2002

Signature:

Printed Names Lynn A. Geiger

Title: Owner

Printed Name: Gerald 188

Title: Owner

Subscribed and provide eering be this 22 day of August 2002

Notary Public, State of

My commission 24

OF WISCO

This document was drafted by the Wisconsin Department of Commerce.

71 hc

1 LZ New